

# HOUSE CALLS INSPECTION, LLC

Website: <http://www.housecallsinspection.com>

Email: [brjhandy@comcast.net](mailto:brjhandy@comcast.net)

Inspector's email: [brjhandy@comcast.net](mailto:brjhandy@comcast.net)

Phone: (423) 314-2114

Inspector's phone: (423) 314-2114

2322 Pineway Trl

Soddy Daisy TN 37379-3256

Inspector: Randy Johnson



## Property Inspection Report # 121101

**Inspectors: Randy Johnson and Mike Pendergrass**

**Structure(s) inspected: Residential dwelling; 1 Level**

**Year Built: 1979**

**Start: 1:00pm End: 4:45pm Weather: Clear, 58F**

**Present: Client and Realtor, Jill Riley**

Client(s): **Amy Watkins**

Property address: **7718 Cove Ridge Dr.**

**Hixson, TN 37343**

Inspection date: **12/19/2011**

This report published on Tuesday, December 20, 2011 2:22:05 PM EST

This report is the exclusive property of this inspection company and the client(s) listed in the report title. Use of this report by any unauthorized persons is prohibited.

---

## **How to Read this Report**

This report is organized by the property's functional areas. Within each functional area, descriptive information is listed first and is shown in bold type. Items of concern follow descriptive information. Concerns are shown and sorted according to these types:

Safety	Poses a risk of injury or death
Major Defect	Correction likely involves a significant expense
Repair/Replace	Recommend repairing or replacing
Repair/Maintain	Recommend repair and/or maintenance
Minor Defect	Correction likely involves only a minor expense

Maintain	Recommend ongoing maintenance
Evaluate	Recommend evaluation by a specialist
Monitor	Recommend monitoring in the future
Comment	For your information

[Click here](#) for a glossary of building construction terms.

---

## **Exterior**

Footing material: Not visible  
 Foundation material: Concrete block  
 Apparent wall structure: Wood frame  
 Wall covering: Stone veneer, Vinyl  
 Driveway material: Asphalt  
 Sidewalk material: Poured in place concrete  
 Exterior door material: Solid core steel.

---

1) *Safety, Repair/Replace, Evaluate* - One or more open ground, three-pronged grounding type receptacles were found. This is a safety hazard due to the risk of shock. A qualified electrician should evaluate and make repairs as necessary.

Grounding type receptacles were first required in residential structures during the 1960s. Based on the age of this structure and/or the absence of 2-pronged receptacles, repairs should be made by correcting wiring circuits as necessary so all receptacles are grounded as per standard building practices. Replacement of three-pronged receptacles with 2-pronged receptacles is not an acceptable solution.

Location of receptacle: left of the rear sliding glass door.

---

2) *Safety, Repair/Replace* - One or more fence gates are difficult to open, close and/or latch, or are damaged and/or deteriorated. Repairs should be made as necessary, and by a qualified contractor if necessary, so gates operate easily.

The fence gate is attached to the vinyl siding, front left. The gate post is not anchored in the ground, and the entire structure is loose.



Photo 46



Photo 47

---

3) *Repair/Maintain* - Soil is in contact with or less than six inches from siding and/or trim. This is a conducive condition for wood destroying insects and organisms. Soil should be graded and/or removed as necessary so there are at least six inches of space between the siding and trim and the soil below.

---

4) *Repair/Maintain* - There is small hole in the stone exterior wall near the garage door. Repair and maintain in order to prevent water, debris and/or vermin intrusion.



Photo 28

---

## **Roof**

Roof inspection method: Traversed

Roof type: Gable

Roof covering: Asphalt or fiberglass composition shingles

Estimated age of roof: 4 years

Gutter & downspout material: Aluminum

Roof ventilation: Adequate Roof vents on both ridges

---

5) *Repair/Replace, Evaluate* - The chimney flashing appears to be installed improperly, and should be checked by a licensed contractor.



Photo 43



Photo 44

---

6) *Maintain, Monitor* - Two sections of roof surfaces are sloped towards each other. Debris such as leaves or needles are more likely to accumulate in this area than rest of the roof. Leaks may occur as a result. Recommend monitoring such areas for accumulated debris in the future and cleaning as necessary.

---

## **Garage**

---

7) *Safety, Repair/Replace, Evaluate* - One or more wall and/or ceiling surfaces between the attached garage and interior living spaces have gaps, holes, or missing or inadequate surface materials. These surfaces are intended to prevent vehicle fumes from entering living spaces, and to slow the spread of fire from the garage to living spaces. A qualified contractor should evaluate and make repairs as necessary so the attached garage wall and ceiling surfaces that adjoin living spaces are tightly sealed and fire rated as per standard building practices. Typically these surfaces require a one-hour fire rating.



Photo 40

---

8) *Safety, Repair/Replace* - One of the receptacles is cracked and broken, and should be replaced.



Photo 41

---

9) *Safety, Repair/Maintain* - The garage door did not reverse upon contact with an object.

---

10) *Major Defect, Evaluate* - The main support beam has been notched in the center, and a

metal jack post has been installed for additional support in the center of the garage.



Photo 39



Photo 48

---

11) *Minor Defect, Monitor* - The rear concrete block wall has a number of step cracks, most of which follow the mortar lines. Most of the cracks are minor, but their condition should be monitored.



Photo 24



Photo 25



Photo 3

---

12) *Minor Defect* - The entry door has a small crack in the frame.



Photo 42

---

## **Attic**

Inspection method: Partially traversed

Roof structure type: Rafters

Ceiling structure: Trusses

Insulation material: Cellulose loose fill. Insulation not adequate

Insulation depth: <3"

---

13) *Safety, Repair/Replace, Evaluate* - Wire splices are exposed due to not being contained in a covered junction box. This is a safety hazard due to the risk of shock and fire. A qualified electrician should evaluate and make repairs as necessary. For example, install securely mounted junction boxes with cover plates where needed to contain wiring splices.



Photo 50

---

14) *Repair/Replace* - The ceiling insulation's R rating is significantly less than what's recommended for this area. Recommend having a qualified contractor install additional insulation as per standard building practices for better energy efficiency.

---

15) *Repair/Maintain, Minor Defect* - Neither of the bathroom exhaust fans is vented properly to the outside.



Photo 20



Photo 21

---

16) *Minor Defect* - No insulation is installed over the attic access hatch. Recommend installing insulation above hatch for better energy efficiency.

---

17) *Minor Defect* - No weatherstrip is installed around the attic access hatch. Weatherstrip should be installed around the hatch to prevent heated interior air from entering attic.

---

18) *Evaluate* - The attic insulation is inadequate-less than 3" in most areas.



Photo 22




Photo 23

Primary service type: Overhead  
Primary service overload protection type: Circuit breakers  
Service amperage (amps): 200  
Service voltage (volts): 120/240  
Location of main service switch: Main panel  
Location of main disconnect: Breaker at top of main service panel  
Service entrance conductor material: Aluminum  
System ground: Ground rod(s) in soil  
Main disconnect rating (amps): 200  
Branch circuit wiring type: Aluminum multi-strand  
Solid strand aluminum branch circuit wiring present: No  
Smoke detectors present: Yes

---

19) *Safety, Repair/Replace, Evaluate* - The service drop wires are less than 10 feet above ground or walkways. This is a safety hazard due to the risk of shock. A qualified electrician and/or the utility company should evaluate and repair as necessary.

---

20) *Safety, Repair/Replace, Evaluate* - One or more overcurrent protection devices (circuit breakers or fuses) are "double tapped", where 2 or more wires are clamped in a terminal designed for only one wire. This is a safety hazard since the bolt or screw may tighten securely against one wire, but leave others loose. Arcing, sparks and fires may result. A qualified electrician should evaluate and repair as necessary.



Photo 1  
Main service panel-one circuit breaker has a double tap (two wires connected to the same breaker)

---

21) *Safety, Repair/Replace* - The service drop wires are in contact with trees or vegetation. Recommend having a qualified tree service company or arborist prune or remove trees as necessary to prevent straining or abrading the service drop wires. The service drop wire has been anchored/ attached to a tree, presumably to raise the height of the wire. Recommend that utility company be contacted to evaluate the problem.



Photo 26

---

22) *Safety, Repair/Maintain* - There is an open splice inside the main panel. Spliced wiring should be enclosed within a junction box.



Photo 2  
Open splice in the electrical  
service panel.

---

23) *Safety, Minor Defect* - One or more screws are missing from the main service panel cover and should be replaced. Because energized wiring may exist behind the holes with the missing screws, recommend that a qualified, licensed electrician replace these screws, or that care be taken to ensure that the new screws do not come in contact with wiring inside the panel when they are installed. Stock screws from the panel manufacturer should be used, or their equivalent.

---

### **Water heater**

Estimated age: 6 years

Type: Tank

Energy source: Electricity

Capacity (in gallons): 50

Manufacturer: U.S. Craftmaster

Model: E1F50RD045

Estimated age: 6 years

Type: Tank

Energy source: Electricity

Capacity (in gallons): 50

Manufacturer: U.S. Craftmaster

Model: E1F50RD045V

Water temperature (degrees Fahrenheit): 119.3 degrees

---

24) *Safety, Repair/Replace, Evaluate* - The unit wiring has an open splice that should be enclosed within a junction box. A qualified electrician should evaluate and repair as necessary.



Photo 49  
( The lower arrow points to  
the pressure relief valve that  
has no extender drain pipe.  
That concern is discussed  
below)

25) *Safety, Repair/Replace* - The water heater does not have seismic straps or struts installed. This is a potential safety hazard since movement can cause leaks in the gas supply lines or damage wiring. Leaks may also occur in water supply pipes. A qualified contractor should install seismic straps or struts as necessary and as per standard building practices.

---

26) *Safety, Repair/Replace* - No drain line is installed for the temperature-pressure relief valve. This is a potential safety hazard due to the risk of scalding if someone is standing next to the water heater when the valve opens. A qualified plumber should install a drain line as per standard building practices. For example, extending to 6 inches from the floor, or routed so as to drain outside.



Photo 7

---

27) *Repair/Replace, Minor Defect* - A water heater is installed and has no catch pan and drain. Recommend having a qualified contractor install a catch pan and drain to prevent water damage inside the garage if/when the water heater develops a leak or is drained.

---

## **Heating and cooling**

Estimated age: 16 years

Primary heating system energy source: Natural gas

Primary heat system type: Forced air

Primary A/C energy source: Electric

Primary Air conditioning type: Split system

Distribution system: Sheet metal ducts

Manufacturer: Carrier

Model: CD5AXA030000AAAA

Filter location: In return air duct above furnace

---

28) *Safety, Repair/Replace, Evaluate* - Some rust and/or corrosion was found on one or more gas supply pipes. Based on this deterioration, the wrong materials may have been used. For example, black iron pipe may have been used where galvanized iron pipe should have been used instead. Leaks may occur as a result. This is a safety hazard. A qualified heating and cooling contractor should evaluate and make repairs as necessary.



Photo 5



Photo 6

---

29) *Safety, Repair/Maintain, Evaluate* - The furnace is equipped with a power venting system that does not appear to be vented to the outside. The manufacturer, Field Controls, Inc., indicates on their website that devices outfitted with their units must still be vented outside in order to prevent accumulation of noxious/ dangerous gases within a closed space/ living areas. Recommend that a qualified HVAC technician evaluate the venting system and properly configure it, if necessary.

Field Controls, Inc.  
2630 Airport Rd.  
Kinston, N.C. 28504  
252-522-3031  
[www.fieldcontrols.com](http://www.fieldcontrols.com)



Photo 4

---

30) *Major Defect, Comment* - The estimated useful life for most forced air furnaces is 15 to 20 years. This furnace appears to be approaching this age and may need replacing at any time. Recommend budgeting for a replacement in the near future.

---

31) *Major Defect, Comment* - The estimated useful life for air conditioning compressors is 8 to 15 years. This unit appears to be approaching this age and may need replacing at any time. Recommend budgeting for a replacement in the near future.

---

32) *Maintain* - Air handler filter(s) are dirty and should be replaced now. They should be checked monthly in the future and replaced as necessary.



Photo 34

---

33) *Comment* - The outdoor air temperature was below 60 degrees Fahrenheit during the inspection. Because of this, the inspector was unable to operate and fully evaluate the cooling system.

---

### **Plumbing and laundry**

Water pressure (psi):

Location of main water shut-off valve: Meter box at street

Location of main water meter: Near street

Water service: Public

Service pipe material: Not visible

Supply pipe material: Copper

Vent pipe material: Plastic

Drain pipe material: Plastic

Waste pipe material: Plastic

---

34) *Safety, Repair/Replace, Evaluate* - The clothes dryer exhaust duct is too long, or has too many bends. This may reduce the air flow through the duct, resulting in overheating, reduced efficiency and/or difficulty in cleaning the duct. Standard building practices limit clothes dryer exhaust ducts to 25 feet, and less when bends are present (2.5 feet for each 45-degree bend and 5 feet for each 90-degree bend). A qualified contractor should evaluate and modify the exhaust duct as per standard building practices.

We could only observe the duct between the dryer and the wall (approximately 6" of length), and where the duct terminates above the garage door. There was also no cover on the end of the duct, which prevents intrusion by vermin or debris.



Photo 27

---

35) *Repair/Maintain, Minor Defect* - One of the laundry room closet doors is partially detached from the frame.



Photo 13



Photo 14

---

36) *Comment* - Neither the clothes washer nor dryer were operated or evaluated. They are excluded from this inspection.

---

### **Fireplaces, woodstoves and chimneys**

Fireplace type: Masonry

Chimney type: Metal

---

37) *Safety* - The chimney should be cleaned and evaluated before using.

---

38) *Monitor* - Minor cracks, pitting and/or deterioration were found in some fireplace firebrick. However the bricks were not loose and appear to be serviceable. The clients should monitor the condition of the firebricks in the fireplace's firebox in the future. If significant deterioration occurs or if bricks become loose, then a qualified chimney service contractor should evaluate and make repairs as necessary.



Photo 9

---

39) *Monitor* - A capped gas supply line, presumably installed for a conversion, extends through the interior wall.



Photo 10

---

### **Crawl space**

Inspection method: Partially traversed  
Insulation material underneath floor above: None visible  
Pier or support post material: Concrete/Concrete block piers  
Beam material: Solid wood  
Floor structure above: Solid wood joists  
Vapor barrier present: Some areas not covered.

---

40) *Safety, Repair/Replace* - An opening under the front porch where the exterior wall meets the foundation allows leaves and debris into the deeper crawl space area adjacent to the basement wall. Recommend that the opening be repaired to prevent further intrusions from the outside.



Photo 16  
Inside crawl space.



Photo 19  
Under front porch.

---

41) *Major Defect, Repair/Replace* - No insulation is installed under the floor in the crawl space. Recommend that a qualified contractor install R19 or better (6" thick fiberglass batt) insulation under the floor for better energy efficiency.

---

42) *Repair/Replace, Evaluate, Monitor* - Evidence of prior water intrusion was found in one or more sections of the crawl space. For example, sediment stains on the vapor barrier or foundation, and/or efflorescence on the foundation. Accumulated water is a conducive condition for wood destroying insects and organisms and should not be present in the crawl space. The client(s) should review any disclosure statements available and ask the property owner(s) about past accumulation of water in the crawl space. The crawl space should be monitored in the future for accumulated water, especially after heavy and/or prolonged periods of rain. If water is found to accumulate, a qualified contractor who specializes in drainage issues should evaluate and repair as necessary. Typical repairs for preventing water from accumulating in crawl spaces include:

- Repairing, installing or improving rain run-off systems (gutters, downspouts and extensions or drain lines)
- Improving perimeter grading
- Repairing, installing or improving underground footing and/or curtain drains

Ideally, water should not enter crawl spaces, but if water must be controlled after it enters the crawl space, then typical repairs include installing trenches, gravity drains and/or sump pump(s) in the crawl space.

---

43) *Repair/Replace* - No vapor barrier is installed in some areas. This is a conducive condition for wood destroying insects and organisms due to the likelihood of water evaporating into the structure from the soil. A qualified contractor should install a vapor barrier where missing. Standard building practices require the following:

- The soil below the vapor barrier should be smooth and free from sharp objects.
- Seams should overlap a minimum of 12 inches.
- The vapor barrier should lap up onto the foundation side walls.

Better building practices require that:

- Seams and protrusions should be sealed with a pressure sensitive tape.
- The vapor barrier should be caulked and attached tightly to the foundation side walls. For example, with furring strips and masonry nails.



Photo 18

---

44) *Repair/Replace* - Water supply pipes are uninsulated. Recommend insulating pipes as necessary for better energy efficiency and to prevent water pipes from freezing.

---

45) *Repair/Maintain, Minor Defect* - One of the crawl space vents, left side, is loose.



Photo 45

---

46) *Maintain, Evaluate, Monitor* - The rear crawl space wall has stains that indicate the possibility of past water intrusion. No water, however, was detected in the crawl space.



Photo 17

---

## **Basement**

Insulation material underneath floor above: Fiberglass roll or batt

Pier or support post material: Bearing wall, Steel

Beam material: Built up wood

Floor structure above: Solid wood joists

---

47) *Safety, Repair/Replace, Evaluate* - One or more notches are cut into the middle third of joist(s), as discussed above in Garage section. This is substandard construction and has damaged the joist(s). A qualified contractor should evaluate and repair as necessary.

---

## **Kitchen**

---

48) *Repair/Replace, Minor Defect* - Dining Room- The cable receptacle is loose.



Photo 38

---

49) *Repair/Maintain, Minor Defect* - The door between the garage steps and the kitchen will not open fully without rubbing the floor.

---

## **Bathrooms**

---

50) *Safety, Repair/Replace, Evaluate* - One or more open ground, three-pronged electric receptacles were found. This is a safety hazard due to the risk of shock. A qualified electrician should evaluate and make repairs as necessary. For example, replacing receptacles or correcting wiring circuits.

Grounding type receptacles began being required in residential structures during the 1960s. Based on the age of this structure and the presence of 2-pronged receptacles in some areas of this structure, an acceptable repair may be to simply replace the ungrounded 3-pronged receptacles with 2-pronged receptacles. However the following appliances require grounding type receptacles:

- Computer hardware
- Refrigerators
- Freezers
- Air conditioners
- Clothes washers
- Clothes dryers
- Dishwashers
- Kitchen food waste disposers
- Information technology equipment
- Sump pumps
- Electrical aquarium equipment
- Hand-held motor-operated tools
- Stationary and fixed motor-operated tools
- Light industrial motor-operated tools
- Hedge clippers
- Lawn mowers

This list is not exhaustive. Grounded circuits and receptacles should be installed in locations where such appliances will be used.

---

51) *Safety, Repair/Replace, Evaluate* - One or more electric receptacles have reverse-polarity wiring, where the hot and neutral wires are reversed. This is a safety hazard due to the risk of shock. A qualified electrician should evaluate and make repairs as necessary.



Photo 29  
Receptacle above sink.

---

52) *Safety, Repair/Replace, Evaluate* - One or more electric receptacles and/or the boxes they are installed in are loose and/or not securely anchored. Wire conductors may be damaged due to repeated movement and/or tension on wires, or insulation may be damaged. This is a safety hazard due to the risk of shock and fire. A qualified electrician should evaluate and repair as necessary.



Photo 30  
Adjacent to tub.

---

53) *Safety* - The single receptacle(which is OK) in the master bath is on the same circuit as the incorrectly wired receptacle in the hall bath. When the incorrectly wired hall bath

receptacle trips the breaker, the master bath receptacle will likewise be inoperative if the breaker is tripped.

---

54) *Repair/Replace* - The hall bath faucet and palte is loose and should be repaired or replaced as necessary.



Photo 32

55) *Repair/Replace* - One or more sink stopper mechanisms are missing, or need adjustment or repair. Stopper mechanisms should be installed where missing and/or repairs should be made so sink stoppers open and close easily.



Photo 33

The hall bath sink stopper is not connected.

56) *Repair/Replace* - The hall bathroom tub drain is clogged or drains slowly. Drain(s) should be cleared as necessary, and by a qualified plumber if necessary.

---

57) *Minor Defect, Monitor* - Both the master and hall bathrooms have small patched or damaged areas, possibly the result of condensation.




Photo 31

Hall bathroom above shower.



Photo 35  
Master bathroom.



Photo 36  
Master bathroom.




Photo 37  
Hall bathroom.

---

## **Interior rooms**

---

58) *Safety, Maintain* - The smoke detector would not test properly for us. Batteries in all the smoke alarms should be replaced after taking occupancy, and annually in the future.

"Chirping" noises emitted from smoke alarms typically indicate that batteries need replacing.

For more information, visit:

<http://www.cpsc.gov/cpsc/pub/pubs/5077.html>

---

59) *Repair/Replace, Minor Defect* - The dimmer switch in the living room does not appear to be working.



Photo 12

---

60) *Repair/Replace, Evaluate* - The sash spring mechanism(s) in one or more windows are broken or loose. A qualified contractor or service technician should evaluate and make repairs as necessary so the window(s) operate as intended (open easily, stay open without support, close easily, etc.).

Some of the windows would remain in the raised position, and at least two two windows could not be opened at all without force. One window in the living room is cracked.



Photo 8

---

61) *Repair/Replace, Evaluate* - Screen(s) in one or more windows are missing. The client(s) should ask the property owner(s) about this. Screens are often removed for window cleaning and they may be stored somewhere. If not, then recommend installing screens where missing.

---

62) *Repair/Replace, Evaluate* - The lock mechanisms on one or more sliding glass doors are inoperable and/or difficult to operate. A qualified contractor should evaluate and repair as necessary.

---

63) *Repair/Replace* - The front entry door will not latch when closed. Repairs should be made as necessary, and by a qualified contractor if necessary. For example, aligning strike plates with latch bolts and/or replacing locksets.



Photo 11

---

64) *Repair/Replace* - The master bedroom closet door knob is missing.



Photo 51

---

65) *Evaluate, Monitor* - The ceiling in the dining room has a small area of damage, cause unknown.



Photo 52

---

#### Summary:

All houses, regardless of age or condition, have both positive qualities to recommend them and negative features which require definition and evaluation. Below are the primary concerns, as well as a list of the best attributes.

#### PRIMARY CONCERNS:

- 1) The middle steel jack post on the main beam in the garage, and the notch in that beam.
- 2) The lack of fire wall protection between the garage and the living area .
- 3) The lack of outside venting for the furnace.
- 4) The electrical service wire anchored on the tree in the yard, and the clearance of less than 10' ( about 8'6" at its lowest point.
- 5) The hot-neutral reverse polarity receptacle in the hall bathroom.

#### POSITIVE ATTRIBUTES:

- 1) The siding is in excellent condition.
- 2) The roof is in good shape.
- 3) The gable and roof vents provide for appropriate ventilation.
- 4) The flooring and carpeting are in good condition.
- 5) The foundation and roof structure appear to be sound.